Dropsonde Scientist

Flight ID 20180708H(Storm Crist Dropsonde Scientist Dropsonde Scientist AND The lead project scientist (LPS) on the P3 is responsible for determining the distribution

The lead project scientist (LPS) on the P3 is responsible for determining the distribution patterns for dropwindsonde releases. Predetermined desired data collection patterns are illustrated on the flight patterns. However, these patterns often are required to be altered because of clearance problems, etc. Operational procedures are contained in the operator's manual. On the G-IV the sole HRD person is designated the LPS. The following list contains more general supplementary procedures to be followed. (Check off or initial.)

Preflight										
1.	Determine the status of the AVAPS and HAPS or workstation. Report results to the LPS.									
2.	Confirm the mission and pattern selection with the LPS and assure that enough dropsondes are on board the aircraft.									
3.	Modify the flight pattern or drop locations if requested by AOC to accommodanges in storm location or closeness to land.									
4.	Complete the appropriate preflight set-up and checklists.									
In-Flight										
1.	Operate the system as specified in the operator's manual.									
2.	Ensure the AOC flight director is aware of upcoming drops.									
3.	Ensure the AVAPS operator has determined that the dropsonde is (or is not) transmitting a good signal. Recommend if a backup dropsonde should be launched in case of failure.									
4.	Report the transmission of each drop and fill in the Dropwindsonde Scientist Log.									
Post flight										
1.	Complete Dropwindsonde Scientist Log.									
2.	Brief the LPS on equipment status and turn in completed forms, dropwindsonde data tapes, DVDs, or CDs.  [Note: all data removed from the aircraft by HRD personnel should be cleared with the AOC flight director.]									
4.	Debrief at the base of operations.									
5.	Determine the status of future missions and notify MGOC as to where you can be contacted.									

N42/3RF HRD GPS Dropwindsonde Scientist Log (Revised 5/2002)

Storm_	CHRIS	Dropwin	dsonde S	cientist	s An	NANE	5			Page	of		
Flight ID 2018 0708 HI Flight Director MIKE HOLMES Takeoff from LAKELAND at \$331 UTC													
Mission ID BACHRIS AVAPS Operators HART BERGER Recovery at at utc													
Drop #	Sonde ID #	Time (UTC)	Lat (°N)	Lon (°W)	Surface Pressure (mb)	Wind clos to surface dir/spd (kt)	ce	BT SST (°C)	Eye, Eyewall, Rainband (direction)	Comments	Ob #		
	164015157	1077	33,10	7259						Red 24) TP		7 0 ~	
2	163845059	10:44	33,28	75,10						Centra durn (Rad	RA	Holas	
3	162715204	1))))	33.29	73.33		784 74 14 CA	和 数 数 数 数			End of EN log.		The	
4	162715785	1159	34,58	75.10	750005 ( 0285 HS 000 77H	MATERIA SA	101000000000000000000000000000000000000	Jacobson Linux	SHERIZARINA SALVAR RIVA STREET	Start of N-S los	and the second second	12 V-9	
1	162 655 180	11257	31.63	75.14						End of Mistage		LISTOTES	
6	163 845 176	13:39	31.66	74.42		a o Asy	W.A. Jen	60000	ing growing a property		11	310	
7	162 735 016	12,:40	32.20	73.39	10703	6/140	10		MA	ie kars	- 12	Asyer	
5	162715 066	14:38	32.99	74.07	1017.5	14/1/1	10	60.76.125	NIF		15	نامريا	
9	163 845 037	14:46	34.04	75.08	1970.1	10/10	10		N/A	The states	s 14	pic V	
10	162 715 001	14:56	33.66	7610	1017.6	you ken	10	745 M250	NIA	Alfitude 6489 Buck	12 12	100	
1/	162 735 019	15:06	32.94	76.47	1017.3	3442	40	All Street	N/A	Margier / Cillian	16	land.	
12	160 215 122	15:16	32.01	76.09	1016.7	392.4/14	110	atharecourse	NIA	5 4 1 1616	7' 17	tatel	
13	163025 071	15:25	31.73	75.32	10/5. 8	247.4/39	10	##! 	NIA	55W	18		
STANSON CANA	Ptts convert was a second of the	Matthews against 22	No. of the second of the second			Tables of Alexander Space		C. Copport W. F. Brown and C.					
		No services	, pulson				DOT Suntant			All the Manager of the County			
3 20 20 20 20 20	CAN land April Cons. Lincoln Const. Const.	Lungary de Green	il fachsles celos	5-100mg-1-0250-9		The state of the s	150000						

41,9321

X